


Printable Ring Size Chart

Measure an existing ring — place it over the circles until one matches the inside edge.



CALIBRATION: this bar must measure exactly 100 mm (10 cm). If not, reprint at 100% scale.



US 3
UK F · EU 44
14.0 mm



US 3.5
UK G · EU 45
14.4 mm



US 4
UK H · EU 47
14.8 mm



US 4.5
UK I · EU 48
15.2 mm



US 5
UK J½ · EU 49
15.6 mm



US 5.5
UK K½ · EU 50
16.0 mm



US 6
UK L½ · EU 52
16.45 mm



US 6.5
UK M½ · EU 53
16.9 mm



US 7
UK N½ · EU 54
17.3 mm



US 7.5
UK O½ · EU 56
17.7 mm



US 8
UK P½ · EU 57
18.1 mm



US 8.5
UK Q½ · EU 58
18.5 mm



US 9
UK R½ · EU 59
19.0 mm




US 9.5
UK S½ · EU 61
19.4 mm




US 10
UK T½ · EU 62
19.8 mm




US 10.5
UK U½ · EU 63
20.2 mm




US 11
UK V½ · EU 65
20.6 mm




US 11.5
UK W½ · EU 66
21.0 mm



US 12
UK X½ · EU 67
21.4 mm



US 12.5
UK Z · EU 68
21.8 mm




US 13
UK Z+1 · EU 70
22.2 mm

Printable Ring Size Chart

Finger measuring strip and full international conversion chart.

Finger measuring strip — cut out, wrap around your finger, read the size at the overlap.



Numbers = inside circumference in millimetres. Match it to the mm column in the chart below.

Dia (mm)	Circ (mm)	US	UK	EU	France	Germany	Switz.	Japan	Brazil
14	44.0	3	F	44	44	14	4	4	7
14.4	45.2	3.5	G	45	45.5	14.5	5.75	5	8
14.8	46.5	4	H	47	46.75	14.75	7	7	9
15.2	47.8	4.5	I	48	48	15.25	8.25	8	10
15.6	49.0	5	J½	49	49.25	15.75	9.5	9	11
16	50.3	5.5	K½	50	50.5	16	10.75	10	12
16.45	51.7	6	L½	52	51.75	16.5	12	12	13
16.9	53.1	6.5	M½	53	53	17	13.25	13	14
17.3	54.3	7	N½	54	54.25	17.25	14.5	14	15
17.7	55.6	7.5	O½	56	55.5	17.75	15.75	15	16
18.1	56.9	8	P½	57	56.75	18.25	17	16	17
18.5	58.1	8.5	Q½	58	58	18.5	18.25	17	18
19	59.7	9	R½	59	59	19	19.5	18	19
19.4	60.9	9.5	S½	61	60.25	19.5	20.75	19	20
19.8	62.2	10	T½	62	61.5	19.75	22	20	21
20.2	63.5	10.5	U½	63	62.75	20.25	23.25	22	22
20.6	64.7	11	V½	65	64	20.75	24.5	23	23
21	66.0	11.5	W½	66	65.25	21	25.75	24	24
21.4	67.2	12	X½	67	66.5	21.5	27	25	25
21.8	68.5	12.5	Z	68	67.75	22	28.25	26	26
22.2	69.7	13	Z+1	70	69	22.25	29.5	27	27

Tip: measure at the end of the day when fingers are largest, and avoid measuring when cold.